



Barrier Bag Handling Instructions

In order to make the most effective use of the barrier bag you have purchased, we recommend that you strictly adhere to all the following instructions.

General Guidelines

Store the barrier bags in a shaded and protected area, laid horizontally on a smooth surface.

Optimal installation temperature is 73°.

Install barrier bag in clean dry area.

Reduce Potential Damage

Do not drag the bag material. Typical dragging damage appears that the foil layer has flaked off. We do not guarantee this kind of damage.

Do not stand on, walk on, or puncture material.

Do not do anything that may scratch the material.

Do not bend or crease material significantly or repeatedly.

Make sure that metal and wood parts that come into contact with the barrier bag are smooth. Cover edges and protruding parts with suitable padding.

Suggested Sealing Conditions

Read the Sealer User Guide before installing the barrier bag.

Heat sealing temperature at 375°F, 40psi, 2.0sec.

The values indicated in this document are the results of tests made in compliance with the normal standards. They are given as an indication and should be considered as average values and given without any obligation on our part.