



Valley Box Company provides you with the right tools to optimize your shipping process and increase your service capabilities, all while increasing efficiency and cutting costs.

Case Study: Corrosion Prevention

CHALLENGE

A Parts Distribution Warehouse needed to decrease their 13% corrosion rate on all stored parts. The company required a product that would remove the corrosion that had taken place, as well as prevent future corrosion. At the forefront were their concerns about their product's multiple metals, sensitive electronic and mechanical components.

BENEFITS

- Prevented all corrosion on parts
- Prevention cost less than reaction
- Protected various metals
- Emitters protected parts with sensitive electronics
- Improved customer relationships
- Vendor surveillance minimized stock shortages

SOLUTION

Valley Box Field Technicians recommended the use of Zerust® a corrosion inhibiting product along with vapor barrier bags. Tech's were able to successfully remove the existing corrosion and a vendor surveillance program kept the Parts Company stocked with emitters, humidity indicators, desiccants, and gusseted barrier bags. Since the implementation of the corrosion prevention solution, the company has decreased part loss to 0%.

TESTIMONIAL

The [Valley Box's crew is] also able to support emergency needs ...without effecting the support in our other areas.



Shipping Coordinator
Parts Distribution Warehouse


RUST
REMOVAL



AIR EVACUATED
GUSSETED
BARRIER BAG



ANTI-CORROSION
PRODUCTS



COMPLETE
CORROSION
REDUCTION